



# WORKING AT ST. CATHARINES

Area of Work: GEN V – Assembly

Eng. Supervisor: Dave Keir | Eng. Mentor: George Shing / Chris Bortolotto

By: Maharshi Patel





**GMC**




GENERAL MOTORS

# PROJECTS UNDERTAKEN


- Reducing Block Scrap – Transmission Dowel Thread Holes (OPEX)
- Updated PFD and PFMEA for Gen-V Assembly
- Cold Test Support

A screenshot of a software interface showing a detailed data table with multiple columns and rows. The table is color-coded with various shades of blue, yellow, and green. The interface includes a header section with labels like 'Test Name', 'Test Date', and 'Test Location'. The table contains numerous columns, some of which are highlighted in different colors, suggesting different categories or statuses. The overall layout is typical of a data management or test execution software.


# REDUCING BLOCK SCRAP – TRANS. THREAD BOLTS




Servo Motor Hoist



Pallet Lift Assist



Pallet Adapter Unit



Adapter Arm

# DECISION MATRIX

Engineering Decision Matrix

Solutions: →			Pallet Lift Unit		Servo Motor Hoist		Pallet Adapter Unit	
Criteria ↓	Weight	Weight (%)	Rating	%	Rating	%	Rating	%
Safety	10	21%	8	17%	9	19%	10	21%
Cost to Implement	9	19%	9	19%	6	13%	4	9%
Return on Investment	7	15%	7	15%	4	9%	3	6%
Performance	8	17%	5	11%	7	15%	8	17%
Complexity	6	13%	6	13%	4	9%	2	4%
Chances of Eliminating "Knack"	7	15%	4	9%	7	15%	7	15%
<b>Total: →</b>	47	100%	39	83%	37	79%	34	72%

1 -> Lowest Concern

10 -> Highest Concern



# PFMEA (PROCESS FAILURE MODE AND EFFECTS ANALYSIS) – STATURE

OLD

Severity Occurrence Detection


Remove timing chain tensioner pin and place to verification chute	Pin not removed	Production Interruption In Station (3)	3	Standardized work not followed	3	Visual Inspection - 100% In-station (7)	7	147	4 Y per shift	E/P at a subsequent location - OP 1275 - Mechanical Plunger error proofing unit
		Vehicle Assembly Repair	7			Automated In process Verification - 100% In Station (3) - sensor in discard chute	7			

NEW

Error Proofing for the Gernade Pin	Rejecting Good Parts	Production Interruption In Station (Go into BYPASSmode)	3	Misalligned Mechanical Plunger	3	Cold Test / BYPASS 1275	2	18
	Accepting Bad Parts	Production Interruption In Station (Go into BYPASS mode)	3	Misalligned Mechanical Plunger	3	Cold Test / BYPASS 1275	2	18




# COLD TEST ACCEPTANCE RATE



No. of Test Conducted before Passing	Frequency in No. of Engines	Percentage of Total	
1	17917	87.68%	
2	1633	7.99%	
3	521	2.55%	
<b>Total of First 3 Test</b>			<b>98.22%</b>
4	137	0.67%	
5	85	0.42%	
6	36	0.18%	
<b>% Engines from 4-6 Tests</b>		<b>1.26%</b>	
<b>% Engines from 1-6 Tests</b>			<b>99.48%</b>
7	23	0.11%	
8	8	0.04%	
9 to 12	23	0.11%	
<b>% Engines from 7-12 Tests</b>			<b>0.26%</b>
<b>TEARDOWN</b>	<b>52</b>	<b>0.25%</b>	
<b>TOTAL ENGINES</b>	<b>20435</b>		

# COLD TEST SUPPORT





Description	Re...	Total	Per...	Stati...
INTAKE Average cyl 8	6026	32	3.39%	28
EXHAUST Leak at co...	6753	24	2.54%	24
OILP3 Corrected span	3617	22	2.33%	15
OILP3 Oil Pressure...	3612	22	2.33%	15
NVH 2 Dynamic Oil ...	3469	21	2.22%	16
INTAKE Pressure di...	6039	17	1.80%	12
NVH2 Head LH Accel...	3042	17	1.80%	0
AFM ON Span of pre...	13...	16	1.69%	0
NVH2 Head LH Accel...	3043	16	1.69%	2
NVH1 Block Accel e...	2234	15	1.59%	3
NVH2 Block Accel e...	2979	13	1.38%	0

TOP N Rejects – Data Analysis


# OTHER WORK UNDERTAKEN

- PFMEA
  - TOP 5 RPN
  - Rework List
  - Risk Limiting Level 1
  - Annual-Internal PFMEA Audit
- Single Spindle Safety Initiative
- Oil Pump Rework Fixture
- Head Sub – OP80 Laser Key Check
  - 6.2L Rejects
- Turn Table Assist for Head Sub Load and Unload (OP10/120)
- Cold Test Support
  - Limit Changing




# SKILLS OBTAINED

- Project Management



- Fastening/Assembly Technique



- Engine Testing (Cold Test)

